

SOK50/16HD 110V 3Pin Industrial Socket Tester



- Tough rubber holster for heavy duty use
- Easy to understand correct / incorrect conditions
- Continuous audible tone indicates correct sequence
- Strong warbling tone indicates faulty condition
- Clearly indicates position of L1, L2 and Centre Tap
- Use with SOK ADP50 for testing 32A industrial sockets
- Secure push fit connection
- Hard wearing flexible cable
- Long life LED's

Instructions for use

Insert plug into socket and switch on supply.

Wait for self check to complete, indicated via LED's flashing red and green. No measurement takes place until after this period.

After self check is complete the LED's and tone of buzzer will indicate correct (continuous tone) or incorrect condition (warble tone).

Use the indication table on the tester to identify correct sequence or fault condition.

The SOK50 can be used in conjunction with the SOK ADP50 for testing 32A industrial sockets.

Socket & See SOK Socket Tester Range

SOK40/16HD: 230V 3 pin industrial socket tester

SOK50/16HD: 110V 3 pin industrial socket tester

SOK60/16HD: 400V 4 pin industrial socket tester

SOK65/16HD: 400V 5 pin industrial socket tester

Socket & See SOK ADP Range

SOK ADP40: Converts 16A tester to 32A (3 pin 230V)

SOK ADP50: Converts 16A tester to 32A (3 pin 110V)

SOK ADP60: Converts 16A tester to 32A (4 pin 400V)

SOK ADP65: Converts 16A tester to 32A (5 pin 400V)